

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2020

Submitted Date:

04/13/2020

Document Number:

689803943

FIELD INSPECTION FORMLoc ID 312995 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10407

Name of Operator: ANTLER ENERGY LLC

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Evans, Clay		antlerenergy@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223241	WELL	PR	11/15/1985	OW	081-06605	POWDER WASH FEDERAL 28-7	PR

General Comment:

COGCC Inspection Report 689803943 Summary

On Tuesday 4/7/2020 at approximately 11:40, I, Inspector Emily Waldron, conducted a field inspection at Antler Energy LLC Powder Wash Federal 28-7, at 05-081-06605 in Moffat County Colorado.

While there, I observed, production.

During this inspection the following possible compliance issues were observed:

No labels on tanks. See photo 2. Install sign to comply with Rule 210.d by 6/12/2020.

Stained soil at wellhead. See photo 3. Comply with Rule 603.f, securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d, and properly dispose of oily waste in accordance with 907.e by 6/30/2017.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 689803943.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No labels on tanks.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	06/12/2020

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at wellhead.		
Corrective Action:	Comply with Rule 603.f . Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly dispose of oily waste in accordance with 907.e.	Date:	06/30/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

	2	HEATED STEEL AST		,	
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities				
Facility ID: 223241	Type: WELL	API Number: 081-06605	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Pumping.			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective

Date: _____

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment: Pit located in tank battery. Two pit id's associated with this location. 100422 and 100425.Corrective
Action

Please provide an update to kris.neidel@state.co.us on the status of these pits. Netting on pits should be maintained in good working order prior to use of pit.
Submit an eForm 15 Pit Report to update COGCC records with current information to comply with rule 903.a.

Date: 11/26/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402368676	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5121686
689803944	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5121681