

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402360965

Date Received:

04/02/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

sabre.beebe@bpx.com

Hughes, Jim

jimo.hughes@state.co.us

Fischer, Alex

alex.fischer@state.co.us

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900824

Inspection Date: 09/11/2019

FIR Submit Date: 09/26/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326167

Location Name: THOMAS JACQUEZ GAS UNIT E-N33N10W Number: 14NESE County: LA PLATA

Qtrqr: NESE Sec: 14 Twp: 33N Range: 10W Meridian: N

Latitude: 37.103177 Longitude: -107.898299

FACILITY - API Number: 05-067-00 Facility ID: 215984

Facility Name: THOMAS JACQUEZ E Number: 1

Qtrqr: NESE Sec: 14 Twp: 33N Range: 10W Meridian: N

Latitude: 37.103177 Longitude: -107.898299

CORRECTIVE ACTIONS:

1 ☒ CA# 131173

Corrective Action: Remove and properly dispose of waste and debris.

Date: 10/04/2019

Response: CA COMPLETED

Date of Completion: 04/01/2020

Final Clean up completed as of 4/1/20 however periodic clean up took place as the pipeline leak work was being

Operator Comment: addressed and as phases of the clean up was completed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 131174

Corrective Action: Boring holes need to be closed or properly fenced and covered to prevent potential human or wildlife from falling in.

Date: 10/04/2019

Response: CA COMPLETED

Date of Completion: 04/01/2020

Operator Comment: Holes were back filled as soon as final sampling was completed. Orange fencing that was installed while awaiting sample result is construction industry standard BMP for open excavations for on going work. All holes were immediately back filled and fencing removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 ☒ CA# 131175

Corrective Action: -Control weeds by 10/4/2019.
-Access road and siphon outlet needs to be reclaimed and seeded no later than 11/15/2019.

Date: 10/04/2019

Response: CA COMPLETED

Date of Completion: 04/01/2020

Operator Comment: BPX retains a professional weed control contract company to treat weeds annually. This location received chemical treatment for weeds on 6/29/2016, 7/26/2017, 7/24/2018, 5/14/2019 and 4/1/20. Most recent application for weed control photo documentation attach from the 4/1/20/20 application. Documentation of treatment provided from contract company on chemical application can be provided upon request. Corrective action has been addressed and attempts to control weeds is being performed on an annual basis. Eradication of weeds on locations is an extended process as Cheat Grass seed bank is viable for 3-5 years and Thistle seed banks are viable for 5+ years. BPX has plans to continue annual weed treatment programs performing efforts to address weeds.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

4 ☒ CA# 131176

Corrective Action: Erosion controls such as straw or jute blanket need to be installed to stabilize bare soils at siphon outlet until sufficiently stabilized with perennial vegetation. This should be installed in coordination with re-seeding efforts at the site.

Date: 11/15/2019

Response: CA COMPLETED

Date of Completion: 04/01/2020

Operator Comment: At the completion of the clean up the area was seeded and mulched directly after in the final phase of the remediation.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

All corrective actions completed in a phased approach as the spill area remediation work was completed and weeds have been treated.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 4/2/2020 5:37:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402360965	FIR RESOLUTION SUBMITTED
402360976	completion of final clean up photos

Total Attach: 2 Files