

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402378821

Date Received:

04/23/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Lindsey Rider

970-285-2711

cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696201185

Inspection Date: 04/09/2020

FIR Submit Date: 04/14/2020

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 448472

Location Name: Mesa Number: F26-697 County: _____

Qtrqr: SENW Sec: 26 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.495078 Longitude: -108.190850

FACILITY - API Number: 05-045- -00 Facility ID: 448472

Facility Name: Mesa Number: F26-697

Qtrqr: SENW Sec: 26 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.495078 Longitude: -108.190850

CORRECTIVE ACTIONS:

1 CA# 137976

Corrective Action: Comply with Rule 1002.b.(2) and remove/separate drill cuttings from topsoil.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/20/2020

Operator Comment: The cuttings have been placed in the cut slopes to prepare the location for Interim Reclamation. The cuttings that were not fully contained within that area have been scraped off and brought back into the cut area. 3 feet of topsoil will be placed on top of the cuttings, the topsoil will be seeded and stabilized.

COGCC Decision: _____

COGCC
Representative:

2 CA# 137977

Corrective Action: Comply with Rule 1002.c and remove/separate drill cuttings from topsoil.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/20/2020

Operator Comment: The cuttings have been placed in the cut slopes to prepare the location for Interim Reclamation. The cuttings that were not fully contained within that area have been scraped off and brought back into the cut area. 3 feet of topsoil will be placed on top of the cuttings, the topsoil will be seeded and stabilized.

COGCC Decision: _____

COGCC
Representative:

3 CA# 137978

Corrective Action: Comply with Rules 603.f and 1003.a

Date: _____

Response: CA COMPLETED

Date of Completion: 04/21/2020

Operator Comment: All unused equipment and debris have been removed from the location. Hoses and tarp were removed 04/15/20. Diesel tank was removed 4/21/20.

COGCC Decision: _____

COGCC
Representative:

4 CA# 137979

Corrective Action: Comply with COGCC 1000 series rules and conduct interim reclamation.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/20/2020

Operator Comment: The interim reclamation is in progress and will be completed within the next couple of weeks.

COGCC Decision: _____

COGCC
Representative:

5 CA# 137980

Corrective Action: Install or repair required BMPs in accordance with Rule 1002.f. Ensure BMPs are installed in accordance with good engineering practices, and maintained in proper functioning condition.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/20/2020

Operator Comment: Additional stormwater controls were installed to prevent sediment from leaving the permitted boundary.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lindsey Rider

Signed:

Title: EHS Lead

Date: 4/23/2020 10:38:57 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description

Total Attach: 0 Files