

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402378821

Date Received:

04/23/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Lindsey Rider

970-285-2711

cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696201185

Inspection Date: 04/09/2020

FIR Submit Date: 04/14/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 448472

Location Name: Mesa Number: F26-697 County: \_\_\_\_\_

Qtrqr: SENW Sec: 26 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.495078 Longitude: -108.190850

FACILITY - API Number: 05-045- -00 Facility ID: 448472

Facility Name: Mesa Number: F26-697

Qtrqr: SENW Sec: 26 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.495078 Longitude: -108.190850

CORRECTIVE ACTIONS:

1 ☒ CA# 137976

Corrective Action: Comply with Rule 1002.b.(2) and remove/separate drill cuttings from topsoil.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 04/20/2020

Operator Comment: The cuttings have been placed in the cut slopes to prepare the location for Interim Reclamation. The cuttings that were not fully contained within that area have been scraped off and brought back into the cut area. 3 feet of topsoil will be placed on top of the cuttings, the topsoil will be seeded and stabilized.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed.

Operator shall not place topsoil directly upon E&P Waste/drill cuttings; Operator shall not place E&P waste in such a manner as to allow commingling, contact with, and contamination of, the topsoil in accordance with 1002.c.

Operator has not provided any documentation within this resolution to show that the CA has been addressed; A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 137977

Corrective Action: Comply with Rule 1002.c and remove/separate drill cuttings from topsoil. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 04/20/2020

Operator Comment: The cuttings have been placed in the cut slopes to prepare the location for Interim Reclamation. The cuttings that were not fully contained within that area have been scraped off and brought back into the cut area. 3 feet of topsoil will be placed on top of the cuttings, the topsoil will be seeded and stabilized.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed.

Operator shall not place topsoil directly upon E&P Waste/drill cuttings; Operator shall not place E&P waste in such a manner as to allow commingling, contact with, and contamination of, the topsoil in accordance with 1002.c.

Operator has not provided any documentation within this resolution to show that the CA has been addressed; A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 ☒ CA# 137978

Corrective Action: Comply with Rules 603.f and 1003.a Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 04/21/2020

Operator Comment: All unused equipment and debris have been removed from the location. Hoses and tarp were removed 04/15/20. Diesel tank was removed 4/21/20.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed.

Operator has not provided any documentation within this resolution to show that the CA has been addressed; A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4 ☒ CA# 137979

Corrective Action: Comply with COGCC 1000 series rules and conduct interim reclamation. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 04/20/2020

Operator Comment: The interim reclamation is in progress and will be completed within the next couple of weeks.

COGCC Decision: **Not Approved**

COGCC Representative: Operator was notified in a phone call dated 4/16/2020 that an Operator response of "Corrective Action Complete" in a resolution is a notification to the State that the corrective action has been addressed in its entirety.

COGCC decision "No Approved". Based on operator comments corrective action has not been completed; A FIRR Form is not the appropriate document for submission of notice for when work will be conducted.

5 ☒ CA# 137980

Corrective Action: Install or repair required BMPs in accordance with Rule 1002.f. Ensure BMPs are installed in accordance with good engineering practices, and maintained in proper functioning condition. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 04/20/2020

Operator  
Comment:

Additional stormwater controls were installed to prevent sediment from leaving the permitted boundary.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed.

Operator has not provided any documentation within this resolution to show that the CA has been addressed; A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lindsey Rider

Signed: \_\_\_\_\_

Title: EHS Lead

Date: 4/23/2020 10:38:57 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402378821	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files