

FORM  
6Rev  
02/20

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402381631

Date Received:

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 16700

Contact Name: KEVIN HEJL

Name of Operator: CHEVRON USA INC

Phone: (970) 250-9554

Address: 100 CHEVRON ROAD

Fax:

City: RANGELY State: CO Zip: 81648

Email: KEVINHEJL@CHEVRON.COM

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-103-07024-00

Well Name: F V LARSON B

Well Number: 16-X

Location: QtrQtr: SESE

Section: 26

Township: 2N

Range: 102W

Meridian: 6

County: RIO BLANCO

Federal, Indian or State Lease Number: 47443

Field Name: RANGELY

Field Number: 72370

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.110390

Longitude: -108.805620

GPS Data: GPS Quality Value: 2.2 Type of GPS Quality Value: PDOP

Date of Measurement: 01/08/2007

GPS Instrument Operator's Name: John Floyd

Reason for Abandonment:



Dry



Production Sub-economic



Mechanical Problems

☐ Other

Casing to be pulled:



Yes



No

Estimated Depth: 6340

Fish in Hole:



Yes



No

If yes, explain details below

Wellbore has Uncemented Casing leaks:



Yes



No

If yes, explain details below

Details:

## Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|-----------|-----------|-----------|----------------|---------------------|------------|
| WEBER     | 6019      | 6378      | 04/22/2020     | CEMENT              | 5560       |

Total: 1 zone(s)

## Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| SURF        | 15           | 10+3/4         | 40.5            | 968           | 650          | 968        | 14         | VISU   |
| 1ST         | 9            | 7              | 23              | 5,336         |              | 5,336      | 14         | CBL    |
| 2ND         | 9            | 7              | 23              | 6,458         | 810          | 6,458      | 5,336      | CBL    |

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 5685 with 30 sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

|   |                          |  |
|---|--------------------------|--|
| Set <u>30</u> sks cmt from <u>5685</u> ft. to <u>5560</u> ft. | Plug Type: <u>CASING</u> | Plug Tagged: <input checked="" type="checkbox"/> |
| Set <u>30</u> sks cmt from <u>3222</u> ft. to <u>3122</u> ft. | Plug Type: <u>CASING</u> | Plug Tagged: <input checked="" type="checkbox"/> |
| Set <u>125</u> sks cmt from <u>1108</u> ft. to <u>871</u> ft. | Plug Type: <u>CASING</u> | Plug Tagged: <input checked="" type="checkbox"/> |
| Set _____ sks cmt from _____ ft. to _____ ft.                 | Plug Type: _____         | Plug Tagged: <input type="checkbox"/>            |
| Set _____ sks cmt from _____ ft. to _____ ft.                 | Plug Type: _____         | Plug Tagged: <input type="checkbox"/>            |

Perforate and squeeze at 3155 ft. with 30 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at 1050 ft. with 60 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. \_\_\_\_\_ inch casing Cut and Cap Date: 04/22/2020

\*Wireline Contractor: Production Logging Services \*Cementing Contractor: BJ Cementing

Type of Cement and Additives Used: 15.8 ppg Plug Cement Class G

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Anita Sanford

Title: Regulatory Tech. Assistan Date: \_\_\_\_\_ Email: atlx@chevron.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Date: \_\_\_\_\_

### CONDITIONS OF APPROVAL, IF ANY:

| COA Type | Description |
|----------|-------------|
|          |             |

### Attachment Check List

| <u>Att Doc Num</u> | <u>Name</u>                 |
|--------------------|-----------------------------|
| 402381967          | LOCATION PHOTO              |
| 402382924          | WELLBORE DIAGRAM            |
| 402382925          | OPERATIONS SUMMARY          |
| 402382945          | CEMENT JOB SUMMARY          |
| 402382965          | WIRELINE JOB SUMMARY        |
| 402383253          | PROPOSED PLUGGING PROCEDURE |

Total Attach: 6 Files

### General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|---------------------|
|                   |                | Stamp Upon Approval |

Total: 0 comment(s)