

FORM

6

Rev  
02/20

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:

402313857

Date Received:

02/18/2020

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 16700

Contact Name: JON BACON

Name of Operator: CHEVRON USA INC

Phone: (970) 687-7282

Address: 100 CHEVRON ROAD

Fax:

City: RANGELY State: CO Zip: 81648

Email: JON.BACON@CHEVRON.COM

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-045-05051-00

Well Name: NAP-GOV'T

Well Number: 1-A

Location: QtrQtr: SESW

Section: 22

Township: 7S

Range: 104W

Meridian: 6

County: GARFIELD

Federal, Indian or State Lease Number: 12464

Field Name: SOUTH CANYON

Field Number: 77750

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.433760

Longitude: -108.976700

GPS Data: GPS Quality Value: 4.7 Type of GPS Quality Value: PDOP

Date of Measurement: 07/15/2012

GPS Instrument Operator's Name: Duane Russell

Reason for Abandonment:



Dry



Production Sub-economic



Mechanical Problems

☒ Other Lease relinquished from operator (Mont Rouge Inc). As record title

Casing to be pulled:



Yes



No

Estimated Depth:

Fish in Hole:



Yes



No

If yes, explain details below

Wellbore has Uncemented Casing leaks:



Yes



No

If yes, explain details below

Details:

## Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
BUCKHORN	4105	4129	02/06/2020	CEMENT	4053

Total: 1 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	10+3/4	8+5/8	28	167	75	167	0	CALC
1ST	7+7/8	5+1/2	15.5	4,188	100	4,188	3,223	CALC

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4051 with 20 sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 25 sks cmt from 3883 ft. to 3664 ft. Plug Type: CASING Plug Tagged: ☒  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at 800 ft. with 156 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☒

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. \_\_\_\_\_ inch casing Cut and Cap Date: 02/06/2020  
of \_\_\_\_\_

\*Wireline Contractor: CUTTERS WIRELINE SERVICE

\*Cementing Contractor: BJ SERVICES

Type of Cement and Additives Used: 15.5 PPG SQUEEZE CEMENT

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

(1/30/2020) - Squeezed ~12 gallons NanoSeal down the 8-5/8 x 5-1/2 annulus. Shut in the well with 780 psi squeeze pressure & left shut in over the weekend to set.

(2/2/2020) - Opened well up (50 psi SISCP, bled off instantly with no fluid returns).

Wellhead cut off 5' below ground level, cap welded on and then backfilled on 2/6/20 with BLM and COGCC witnesses. Reclamation is pending.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: ANITA SANFORD

Title: REGULATORY TECH.ASSISANT Date: 2/18/2020 Email: ATLX@CHEVRON.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Katz, Aaron Date: 5/4/2020

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

--	--

### Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
402313857	FORM 6 SUBSEQUENT SUBMITTED
402313868	CEMENT BOND LOG
402313872	LOCATION PHOTO
402313888	OPERATIONS SUMMARY
402313893	WELLBORE DIAGRAM
402313935	OTHER
402313937	CEMENT JOB SUMMARY

Total Attach: 7 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	Need production data updated - emailed teri 4/30/2020 - approved once production reporting is updated  This well was plugged by Chevron, but operated by Mont Rouge Inc.  Adjusted input to correct line on plugging procedure  WBD and ops summary reviewed.  updated scout card with PA/AB status and removed duplicate casing entries	04/30/2020

Total: 1 comment(s)