

APACHE CANYON 07-05 API# 05-071-08652 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102498



PHOTO 1: THE RISER IS A LOW POINT DRAIN AND IS IN USE. THE RISER WAS LABELED AS TO THE FUNCTION FOR CLARITY.

APACHE CANYON 07-05 API# 05-071-08652 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102498



PHOTO 2: THE RISER IS A LOW POINT DRAIN AND IS IN USE. THE RISER WAS LABELED AS TO THE FUNCTION FOR CLARITY.

APACHE CANYON 07-05 API# 05-071-08652 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102498



PHOTO 3: THE BELT GUARD HAD BEEN REMOVED FROM THE PUMPING UNIT FOR MAINTENANCE TO THE CLUCH. THE BELT GUARD WAS PLACED BACK ON THE UNIT.

APACHE CANYON 07-05 API# 05-071-08652 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102498



PHOTO 4: MAINTENANCE WAS PREFORMED ON THE LIQUID RING COMPRESSOR. THE FLUID ACCUMULATION WAS REMOVED AND THE SKID WAS CLEANED.