

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402389176

Date Received:  
05/04/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergyllc.com</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695102494  
Inspection Date: 03/31/2020 FIR Submit Date: 03/31/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 307292

Location Name: APACHE CANYON-634S68W Number: 12SWNW County: LAS ANIMAS  
Qtrqtr: SWN Sec: 12 Twp: 34S Range: 68W Meridian: 6  
W  
Latitude: 37.101880 Longitude: -104.954770

FACILITY - API Number: 05-071- -00 Facility ID: 217394

Facility Name: APACHE CANYON Number: 12-5  
Qtrqtr: SWN Sec: 12 Twp: 34S Range: 68W Meridian: 6  
W  
Latitude: 37.101880 Longitude: -104.954770

CORRECTIVE ACTION:

1 CA# 137635

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

Operator Comment: Maintenance was conducted to stop the leaks on the liquid ring compressor. The fluid accumulation in the containment of the liquid ring compressor was removed and the skid was cleaned. The impacted soil around the liquid ring was removed from location. See attached photo log for details.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: SR. Environmental Tech.

Date: 5/4/2020 3:40:27 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402389193	Photo Log
-----------	-----------

Total Attach: 1 Files