

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402318047

Date Received:  
05/14/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 679602292  
Inspection Date: 02/11/2020 FIR Submit Date: 02/11/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SRC ENERGY INC Company Number: 10311  
Address: 1675 BROADWAY SUITE 2600  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 319579

Location Name: Greeley-Rothe Number: 1H County: \_\_\_\_\_  
Qtrqr: SESE Sec: 1 Twp: 5N Range: 67W Meridian: 6  
Latitude: 40.423345 Longitude: -104.834751

FACILITY - API Number: 05-123-00 Facility ID: 319579

Facility Name: Greeley-Rothe Number: 1H  
Qtrqr: SESE Sec: 1 Twp: 5N Range: 67W Meridian: 6  
Latitude: 40.423345 Longitude: -104.834751

CORRECTIVE ACTIONS:

1 CA# 136481

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Date: 01/05/2020

Response: CA COMPLETED Date of Completion: 05/10/2020

Operator Comment: Berms have been repaired. Please see attached pictures.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 136482

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 03/11/2020

Response: CA COMPLETED

Date of Completion: 05/10/2020

Operator  
Comment: Berms have been repaired. Please see attached pictures.

COGCC Decision:

COGCC  
Representative:

**3** CA# 136483

Corrective Action: Implement actions to fully comply with Rule 606A regarding fire prevention and protection.

Date: 02/18/2020

Response: CA COMPLETED

Date of Completion: 05/10/2020

Operator  
Comment: Tank has been grounded. Please see attached pictures.

COGCC Decision:

COGCC  
Representative:

**4** CA# 136484

Corrective Action: Comply with Rule 603.f.

Date: 01/05/2020

Response: CA COMPLETED

Date of Completion: 05/10/2020

Operator  
Comment: Weeds have been removed from location. Please see attached pictures.

COGCC Decision:

COGCC  
Representative:

**5** CA# 136485

Corrective Action: Comply with Rule 603.f.

Date: 02/18/2020

Response: CA COMPLETED

Date of Completion: 05/10/2020

Operator  
Comment: Unused equipment have been removed from location. Please see attached pictures.

COGCC Decision:

COGCC  
Representative:

**6** CA# 136486

Corrective Action: Install sign to comply with Rule 210.b.

Date: 01/05/2020

Response: CA COMPLETED

Date of Completion: 05/10/2020

Operator  
Comment:

Wellhead signs have been installed. Please see attached pictures.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 5/14/2020 2:12:37 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402398728	CA PIC1
402398729	CA PIC2
402398730	CA PIC3
402398732	CA PIC4
402398733	CA PIC5
402398734	CA PIC6

Total Attach: 6 Files