

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/20/2020

Submitted Date:

05/26/2020

Document Number:

693901828**FIELD INSPECTION FORM**Loc ID 326678 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Walt	970-385-1372	wabrown@fs.fed.us	
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
,		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262345	WELL	PR	07/01/2017	GW	067-08678	GEARHART 01-32 2	RI

General Comment:

On 5/20/2020 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

-Weeds need to be controlled by 6/15/2020.

-Erosion controls need to be applied to soil stockpiles by 6/30/2020.

See below, and attached photos for additional detail.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? In _____ 1003c. Compacted areas have been cross ripped? _____ 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____ Cuttings management: _____ 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In _____ Production areas have been stabilized? _____ Segregated soils have been replaced? _____	
--	--

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____	Recontoured _____	Perennial forage re-established _____
-------------------------	-------------------	---------------------------------------

Non-Cropland

Top soil replaced _____	Recontoured _____	80% Revegetation _____
-------------------------	-------------------	------------------------

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment: Approximately 150 musk thistles observed within the project area. Revegetation is progressing within the interim reclamation area, although soil stockpiles in the southern project area are weedy and are not stabilized with desirable vegetation (see stormwater below).

Corrective Action: Control weeds. Date **06/15/2020**

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
---------------------------------------	---

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____	Pit mouse/rat holes, cellars backfilled _____	
Debris removed _____	No disturbance /Location never built _____	
Access Roads Regraded _____	Contoured _____	Culverts removed _____
Gravel removed _____		
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____	
Compaction alleviation _____	Dust and erosion control _____	
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____	
Weeds present _____	Subsidence _____	

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Soil stockpiles are not stabilized within the southern project area (southeastern and southwestern). Vegetation on stockpiles is largely annual weeds such as Russian thistle.

Corrective Action: Revegetation needs to be conducted for long term stabilization on soil stockpiles. Stormwater controls (ie: wattles) and eroison controls (ie mulch) are needed until stabilized with desirable perennial vegetation.

Date: 06/30/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693901829	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5158841