

TEP ROCKY MTN LLC - ANNUAL REPORT OF CHANGE 2019-12 OVERVIEW
GL_TrailRidge - Facility ID #464251

Mod Type	ModDescription
New Install	Extended existing line from edge of location to separators (TR 23-22-597 #452055)
New Install	Installed new line from relocated separator to tie-in (TR 1-24-597 #323928)
New Install	Installed new discharge and suction lines from compressor station (TR 44-35-597 #324298)
Modify Line	Abandoned existing line with concrete and installed replacement line along a different route
Modify Line	Replaced existing lines with same material and size