

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2020

Submitted Date:

05/26/2020

Document Number:

700600118**FIELD INSPECTION FORM**Loc ID 308297 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Allison, Rick		rick.allison@state.co.us	
Inspections, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>
Ramsay, David		Dave.ramsay@everwest.com	

**General Comment:**

This is an environmental inspection to document status of a reported spill on the Butch 33-10 TR location reported vial the COGCC complaint system (Complaint 200448966). Follow up with operator indicated that the source of spill was a pinhole leak of hydraulic fluid. Leaked fluid volume was not over the reporting threshold for reporting to the COGCC or Colorado Department of Public Health and Environment (CDPHE).

Operator conducted surface remediation and impacted soils have been removed from the location. Shallow excavation in spill area by COGCC Environmental Inspector did not find any remaining impacts in spill area. Operator is conducting an internal investigation into the cause of the spill to prevent future occurrences or similar spill.

Attached photos show site at the time of inspection. Complaint 200448966 will be closed as a result of this inspection and operator clean up of spill area.

**Environmental****Spills/Releases:**

Type of Spill: NON E&amp;P WASTE

Estimated Spill Volume: 5

Comment: Spill of fluid from equipment on location reported via COGCC complaint system.

Corrective Action: Investigation conducted by operator indicate that spilled fluid was hydraulic fluid. Spills of non exploration and production waste are reportable to CDPHE and are not regulated by the COGCC. Spill is not of a high enough volume to be reportable to CDPHE. Operator has conducted clean up of spill at the time of this inspection. No further corrective action required at this time.

Date: 05/27/2020

Reportable: NO

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

**Water Well Complaint:**

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

**Field Parameters:**

Sample Location:

Comment:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402405725	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5158753">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5158753</a>
700600119	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5158751">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5158751</a>