

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402411981

Date Received:

06/03/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Chris Patterson</u>	<u>970-675-3814</u>	<u>spwu@chevron.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696201221

Inspection Date: 04/28/2020

FIR Submit Date: 05/01/2020

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 314456

Location Name: UNION PACIFIC-62N102W Number: 21SENW County: _____

Qtrqr: SENW Sec: 21 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.130561 Longitude: -108.850661

FACILITY - API Number: 05-103-00 Facility ID: 314456

Facility Name: UNION PACIFIC-62N102W Number: 21SENW

Qtrqr: SENW Sec: 21 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.130561 Longitude: -108.850661

CORRECTIVE ACTIONS:

1 CA# 138579

Corrective Action: Comply with Rule 1004.a and conduct additional reclamation activities; Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed

Date: 07/31/2020

Response: CA COMPLETED

Date of Completion: 06/19/2020

Location was seeded and BMP's Installed/repared. Location to be monitored until proper vegetative coverage. Work was completed using the Chevron Work Order System.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Location was seeded and BMP's Installed/repared. Location to be monitored until proper vegetative coverage. Work was completed using the Chevron Work Order System.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed:

Title: HES Specialist

Date: 6/3/2020 11:30:41 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files