

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402412165

Date Received:
06/04/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Alyssa Beard</u>	<u>3032448114</u>	<u>abeard@foundationenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689804195
Inspection Date: 05/27/2020 FIR Submit Date: 05/29/2020 FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 313253

Location Name: LION GOVERNMENT-612N101W Number: 36NESW County: MOFFAT
Qtrqr: NESW Sec: 36 Twp: 12N Range: 101W Meridian: 6
Latitude: 40.954900 Longitude: -108.699480

FACILITY - API Number: 05-081-00 Facility ID: 282035

Facility Name: LION GOVERNMENT Number: 23-36
Qtrqr: NESW Sec: 36 Twp: 12N Range: 101W Meridian: 6
Latitude: 40.954900 Longitude: -108.699480

CORRECTIVE ACTIONS:

1 CA# 139377

Corrective Action: Immediately comply with material handling and guidance per MSDS or product data sheet. Submit document, procedures, and waste disposal manifest to COGCC field inspector.

Date: 06/09/2020

Response: CA COMPLETED Date of Completion: 06/01/2020

Operator Comment: Halliburton mobilized to location to remove their equipment on 6/1/20. The port-a-potty vendor is working to get a driver there to pick it up -can provide an update on that when it has been removed. Removal of the frac sand is documented in CA 139378.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 139378

Corrective Action: Comply with Rule 603.f .

Date: 06/29/2020

Response: CA COMPLETED

Date of Completion: 06/02/2020

Operator
Comment: The SDS was reviewed for proper handling procedures. The sand was wet down to minimize dust, and proper PPE was worn during removal activities to protect workers from any inhalation risk. The leftover sand was containerized and transported to the R360 disposal facility in La Barge, WY. A waste manifest is attached. A photo documenting the current appearance of the location is attached.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 139379

Corrective Action: Comply with Rule 603.f .
Properly dispose of oily waste in accordance with 907.e.

Date: 06/15/2020

Response: CA COMPLETED

Date of Completion: 06/02/2020

Operator
Comment: The stained soil at the wellhead has been removed. Two photos of the wellhead now are attached.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed: _____

Title: EHRS Manager

Date: 6/4/2020 4:13:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402412199	Waste Manifest
402412200	SDS
402412202	Location Photo
402413779	Wellhead Photo - Stained soil removed
402413780	Wellhead Photo - Stained soil removed

Total Attach: 5 Files