

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402425895

Date Received:
06/18/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 5950 CEDAR SPRINGS ROAD
City: DALLAS State: TX Zip: 75235
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Michael Cugnetti</u>	<u>720-845-6901</u>	<u>mcugnetti@verdadresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696301864
Inspection Date: 05/22/2020 FIR Submit Date: 05/22/2020 FIR Status: _____

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC Company Number: 10651
Address: 5950 CEDAR SPRINGS ROAD
City: DALLAS State: TX Zip: 75235

LOCATION - Location ID: 432178

Location Name: SCHNEIDER Number: 1414 County: _____
Qtrqr: NENW Sec: 14 Twp: 8N Range: 60W Meridian: 6
Latitude: 40.669101 Longitude: -104.062588

FACILITY - API Number: 05-123-00 Facility ID: 432178

Facility Name: SCHNEIDER Number: 1414
Qtrqr: NENW Sec: 14 Twp: 8N Range: 60W Meridian: 6
Latitude: 40.669101 Longitude: -104.062588

CORRECTIVE ACTIONS:

1 CA# 139251

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

Date: 06/26/2020

Response: CA COMPLETED Date of Completion: 06/15/2020

Operator Comment: All stained soil at wellheads, engine exhaust and loadlines was removed and properly disposed of. See attached Corrective action photos for documentation.

COGCC Decision: _____

--

Date: 6/18/2020 1:18:33 PM

Total Attach: 5 Files