

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402306768

Date Received:

02/11/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Victoria Dizghinjili

303-825-4822

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693501480

Inspection Date: 10/01/2019

FIR Submit Date: 10/01/2019

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 332926

Location Name: CLEVELAND-62N67W Number: 28NWNW County: WELD

Qtrqr: NWN Sec: 28 Twp: 2N Range: 67W Meridian: 6
W

Latitude: 40.114680 Longitude: -104.903330

FACILITY - API Number: 05-123- -00 Facility ID: 241391

Facility Name: CLEVELAND Number: 8

Qtrqr: NWN Sec: 28 Twp: 2N Range: 67W Meridian: 6
W

Latitude: 40.114680 Longitude: -104.903330

CORRECTIVE ACTIONS:

1 ☒ CA# 131278

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 09/16/2019

Response: CA COMPLETED

Date of Completion: 01/21/2020

Operator Comment: Stained soil has been removed at well head. Please see attached pictures.

COGCC Decision: Approved

COGCC Representative: Based on Photos subitted by operator all corrective actions appear to have been completed. See inspection Doc#693503030.

2 ☒ CA# 131280

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A

Date: 09/16/2019

Response: CA COMPLETED

Date of Completion: 01/20/2020

Operator Comment: Stained soil under PU motor has been removed. Please see attached pictures.

COGCC Decision: Approved

COGCC Representative: Based on Photos subitted by operator all corrective actions appear to have been completed. See inspection Doc#693503030.

3 ☒ CA# 131371

Corrective Action: Install sign to comply with Rule 210.b.

Date: 11/01/2019

Response: CA COMPLETED

Date of Completion: 01/20/2020

Operator Comment: Emergency contact sign has been installed. Please see attached pictures.

COGCC Decision: Approved

COGCC Representative: Based on Photos subitted by operator all corrective actions appear to have been completed. See inspection Doc#693503030.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 2/11/2020 12:51:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402306768	FIR RESOLUTION SUBMITTED
402309375	Sign installed PIC1
402309377	Sign installed PIC2
402309378	Sign installed PIC3
402309380	Sign installed PIC4

Total Attach: 5 Files