

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402431143

Date Received:

06/25/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 700900054
Inspection Date: 03/05/2020 FIR Submit Date: 03/06/2020 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 427862

Location Name: Brown Number: 13-8 County: ADAMS
Qtrqr: SESW Sec: 8 Twp: 1S Range: 67W Meridian: 6
Latitude: 39.974901 Longitude: -104.916112

FACILITY - API Number: 05-001-00 Facility ID: 427854

Facility Name: Brown Number: 11-8
Qtrqr: SESW Sec: 8 Twp: 1S Range: 67W Meridian: 6
Latitude: 39.974901 Longitude: -104.916112

CORRECTIVE ACTIIONS:

1 CA# 136999

Corrective Action: Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O. See photos #7 & 8.

Date: 03/13/2020

Response: CA COMPLETED Date of Completion: 06/16/2020

Operator Comment: Bullplugs have been installed in loadlines. Please see attached picture

COGCC Decision: _____

COGCC
Representative:

2 CA# 137000

Corrective Action: Measure gas per Rule 329. Corrective action date. See photo #5.

Date: 04/06/2020

Response: CA COMPLETED

Date of Completion: 06/15/2020

Operator Comment: Meter is a property of DCP. KPK has submit a request to DCP to have the meter calibrated to comply with Rule 329.

COGCC Decision:

COGCC
Representative:

3 CA# 137001

Corrective Action: Location is within a designated setback location, remove trash or debris per Rule 604.c.(2)P.Corrective action Date See photo #4.

Date: 03/26/2020

Response: CA COMPLETED

Date of Completion: 06/15/2020

Operator Comment: Trash have been removed from location including separator house and meter house. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

4 CA# 137002

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 6. 5.d. Corrective action date.4/6/2020 See photo #9.

Date: 04/06/2020

Response: CA COMPLETED

Date of Completion: 06/15/2020

Operator Comment: Pulley guards have been installed. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

5 CA# 137003

Corrective Action: Spills/Releases (under separator fire tube) Control and contain spills/releases and clean up per Rule 906.a. See photo #3.

Date: 04/06/2020

Response: CA COMPLETED

Date of Completion: 06/15/2020

Operator Comment: Stained soil under separator has been removed. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: Engineering ech

Date: 6/25/2020 11:44:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402431156	CA completed PIC1
402431160	CA completed PIC2
402431162	CA completed PIC3
402431163	CA completed PIC4

Total Attach: 4 Files