

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402442659

Date Received:

07/14/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071 Contact Name and Telephone:  
Name of Operator: HIGHPOINT OPERATING CORPORATION Name: \_\_\_\_\_  
Address: 555 17TH ST STE 3700 Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
City: DENVER State: CO Zip: 80202 Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Doug Dennison</u>	<u>970-353-0407</u>	<u>ddennison@hpres.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901832  
Inspection Date: 05/27/2020 FIR Submit Date: 05/28/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 418076

Location Name: Cox Number: 2-12-39-18 County: DOLORES  
Qtrqtr: NWNE Sec: 12 Twp: 39N Range: 18W Meridian: N  
Latitude: 37.660089 Longitude: -108.780422

FACILITY - API Number: 05-033-00 Facility ID: 412474

Facility Name: Cox Number: 2S-12-39-18  
Qtrqtr: NWNE Sec: 12 Twp: 39N Range: 18W Meridian: N  
Latitude: 37.660089 Longitude: -108.780422

CORRECTIVE ACTIIONS:

1 CA# 139391

Corrective Action:

Date: 06/30/2020

-Conduct soil sampling to determine the likely cause of poor revegetation. As described below, results shall be submitted with a remediation/reclamation plan for the project area.

-Submit a plan to remediate and reclaim the project area. Plan needs to include at a minimum, the following:

- Copies of any soil testing results from testing that was previously conducted at the location.
- Soil sample results from 2020 soil sampling in response to this inspection.
- A detailed soil remediation and reclamation plan based on soil sampling results.
- Schedule to conduct soil remediation activities and reclamation activities in coordination with surface owner and crop timing at all phases of remediation/reclamation.
- A soil/remediation area map

Response: CA COMPLETED

Date of Completion: 06/09/2020

Operator Comment: FIR 693901832 – Cox 2S-12-39-18

HighPoint Resources' reclamation consultant performed periodic monitoring of this location in June, 2020, and a report of their findings is included with this response. The consultant collected soil samples from both the project area and an adjacent undisturbed area, and the results are provided in the included report. Based on their observations and the results for the soil samples, the consultant is recommending the application of Phosphate in late fall 2020 with possibility of a spring 2021 foliar treatment of copper based on observations from monitoring to be conducted in the fall of 2020. All treatments and other future work will be coordinated with and approved by the landowner and/or tenant farmer. Regular monitoring of reclamation success will continue until such time the reclaimed area meets the 1004 reclamation standards.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attachments for site specific information.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Doug Dennison

Signed: \_\_\_\_\_

Title: Dir. Community Affairs

Date: 7/14/2020 10:45:19 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402442783	Soil Recommendations Report
402442821	on site 2020 soil data
402442842	off site 2020 soil data

Total Attach: 3 Files