

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/29/2020

Submitted Date:

07/29/2020

Document Number:

687400816**FIELD INSPECTION FORM**Loc ID 428987 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 200077Name of Operator: CHARLES P DUNNING LLCAddress: PO BOX 1365City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dunning, Chuck	303-408-2575	chuck.dunning@me.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428988	WELL	PR	06/25/2013	OW	001-09750	IKEY 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Adequate
Corrective Action:	Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	50 gallon drum not in secondary containment		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).	Date:	08/28/2020

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 428988 Type: WELL API Number: 001-09750 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On (Tuesday) (07/14/2020) at approximately (11:30am), I, Inspector (Keith Huck), conducted an on-site inspection at (Ikey#1) (Charles P. Dunning), at (Location#428987) in (Adams County) Colorado.</p> <p>While there, I observed (Pumpjack)</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>2nd 50 gallon drum not in secondary containment.</p> <p>Repair or install berms or other secondary containment devices per Rule 906.d.(1).</p> <p>Corrective Action Date 08/28/2020. See Photo#2</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	huckk	07/29/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400817	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213428