

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/01/2020

Submitted Date:

07/29/2020

Document Number:

700300058

**FIELD INSPECTION FORM**

Loc ID 309370 Inspector Name: LABOWSKIE, STEVE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10369  
Name of Operator: NATURAL RESOURCE GROUP INC  
Address: 801 WEST MINERAL AVE STE 202  
City: LITTLETON State: CO Zip: 80120

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293813	WELL	SI	08/01/2017	GW	071-09451	MIRAH 1	SI

**General Comment:**

FLIR inspection to determine extent of venting and fugitive emissions. This inspection does not address corrective actions prescribed in recent inspections, conditions have not change, all corrective actions are still valid and required.

No Form 44 domestic tap registration

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	YES		
Comment:	uncontrolled venting through poly line that had been disconnected by landowner		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 293813 Type: WELL API Number: 071-09451 Status: SI Insp. Status: SI

**Producing Well**

Comment: Valves open and gas supplied to domestic poly line and to high pressure vessel which was venting through and open line with no PRV plumbed down toward ground

Corrective Action: Do not supply gas to domestic tap or tank, well must remain shut in, no viable operator.

Date:

