

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2020

Submitted Date:

08/13/2020

Document Number:

699700189

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Dooling, Jessica	970-675-4122	jessica_dooling@xtoenergy.com	Piceance EHS Supervisor
Merlin Rasmussen		Merlin_rasmussen@xtoenergy.com	SSHE Coordinator

**General Comment:**

On July 28, 2020, COGCC Environmental Staff (John Heil) conducted an Environmental field inspection of XTO ENERGY INC (XTO operator #100264) Yellow Creek Compressor Spill/Release ID 477401. Personnel with XTO were also onsite excavating the spill/release area at time of inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	corrective date
Compressor		
Comment: <span style="color: blue;">The operator is not in compliance with Rule 313.B.</span>		
Corrective Action:	<span style="color: red;">Within 14-days of receiving this Field Inspection Report, the operator shall bring this compressor station into compliance per Rule 313.B., notifying Debbie Lutz, Alex Fischer, and John Heil when the Form 12 has been submitted.</span>	Date: <u>08/27/2020</u>

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date: _____

**Flaring:**

Type		
Comment:		
Corrective Action:		Date: _____

**Environmental**

**Spill/Remediation:**

Comment: See Spill/Release ID 477401 for more information.  
 7/28/2020 COGCC staff observed an excavation located at the southwest corner of the YELLOW CREEK BRIDGE GAS PLANT (Facility ID 434309). Hydrovac material was stockpiled in a steel container and the excavated material was partially stockpiled on liner material. Both hydrovac and excavated material had a detectable hydrocarbon odor and some potential staining was observed. Impacted material from the spill/release was inadequately contained within the liner material.

Corrective Action: Properly store E&P waste per Rule 907.a and clean up per Rule 906.a.  
 Location surface shall be sampled in areas where the impacted material was not properly stored on the liner material.

Date: 09/13/2020

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700191	20200728 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223500</a>