

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402388540

Date Received:

05/04/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ray, Mandy

(505) 599-4083

mray@hilcorp.com

Shorty, Priscilla

pshorty@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901570

Inspection Date: 03/24/2020

FIR Submit Date: 03/30/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325952

Location Name: ALLISON UNIT-N32N6W Number: 19SWNW County: LA PLATA

Qtrqr: SWN Sec: 19 Twp: 32N Range: 6W Meridian: N
W

Latitude: 37.003130 Longitude: -107.547180

FACILITY - API Number: 05-067- -00 Facility ID: 215627

Facility Name: ALLISON UNIT Number: 136

Qtrqr: SWN Sec: 19 Twp: 32N Range: 6W Meridian: N
W

Latitude: 37.003130 Longitude: -107.547180

CORRECTIVE ACTIONS:

1 ☒ CA# 137550

Corrective Action:

Date: _____

-Control weeds. Note that integrated weed management methods are likely needed for jointed goatgrass control and are primarily focused on preventing seed dispersal in spring.

-Revegetation needs to be conducted in portions of the well pad with little to no vegetative cover. Revegetation needs to be monitored by qualified personnel, knowledgeable of revegetation and weeds, and managed as needed to ensure that revegetation is increasing. Documentation of monitoring may be requested.

-Unused equipment needs to be removed

Response: CA COMPLETED

Date of Completion: 05/04/2020

Operator Comment: Revegetation with mulch is completed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 137551

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area.

Date: _____

Response: CA COMPLETED

Date of Completion: 05/04/2020

Operator Comment: Stormwater controls have been installed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 5/4/2020 12:21:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402388540	FIR RESOLUTION SUBMITTED
402388558	Allison Unit 136_Resolved Photos

Total Attach: 2 Files