

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/24/2020

Submitted Date:

08/24/2020

Document Number:

693503391

FIELD INSPECTION FORM

Loc ID 335591 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10454
Name of Operator: PETROSHARE CORPORATION
Address: 9635 MAROON CIRCLE #400
City: ENGLEWOOD State: CO Zip: 80112

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager
GRIMES, MEGHAN		mgrimes@petrosharecorp.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284353	WELL	SI	04/01/2020	GW	001-09563	GUTHRIE 42-2	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds starting to grow on access road need to address in near future.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 284353 Type: WELL API Number: 001-09563 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well was shut in because of operator fracing in area.

Corrective Action: _____ Date: _____

Workover

Comment: Brigade workover rig pulling bridge plug set because of other operator fracing in area. Well is being worked on to put back into production.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Routine inspection. Brigade workover rig pulling bridge plug set because of other operator fracing in area. Well is being worked on to put back into production. Weather conditions: smokey and location is dry.	silverr	08/24/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503392	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230599