

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402405486

Date Received:

05/26/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69805

Name of Operator: PETROX RESOURCES INC

Address: 12600 W COLFAX AVENUE #C-440

City: LAKEWOOD State: CO Zip: 80215

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Nystrom, Dusty</u>	<u>5053301328</u>	<u>nystrow@yahoo.com</u>
<u>Clark, Mike</u>	<u>9708785594</u>	<u>mike.petrox@gmail.com</u>
<u>Clark, Ryan</u>	<u>3038033998</u>	<u>Ryan@Petrox-Resources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901800

Inspection Date: 05/15/2020

FIR Submit Date: 05/18/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PETROX RESOURCES INC

Company Number: 69805

Address: 12600 W COLFAX AVENUE #C-440

City: LAKEWOOD State: CO Zip: 80215

LOCATION - Location ID: 320919

Location Name: TIERRA PIEDRA 33-5 Number: 15-1 SWD County: ARCHULETA

Qtrqr: NWN Sec: 15 Twp: 33N Range: 5W Meridian: N

Latitude: 37.110940 Longitude: -107.385580

FACILITY - API Number: 05-007- -00 Facility ID: 298977

Facility Name: TIERRA PIEDRA 33-5 Number: 15-1 R

Qtrqr: NWN Sec: 15 Twp: 33N Range: 5W Meridian: N

Latitude: 37.110940 Longitude: -107.385580

CORRECTIVE ACTIONS:

1 ☒ CA# 139127

Corrective Action: Control weeds. Subsequent treatments will be needed.

Date: 06/01/2019

Response: CA COMPLETED

Date of Completion: 05/15/2020

Weeds within the Tierra Piedra Well Pad were sprayed on the morning of 5/15/20. Pictures taken on 5/22/20 within the reclamation area already showing considerable weed death. This location was also sprayed during the

Operator Comment: spring and fall of 2019. The area outside of the fence and to the south, where the inspector showed the majority of the weeds, is outside the reclamation area (as built drawing on file with the COGCC and reattached to this FIRR). The western and southern berm was paid for and constructed by the Tierra Piedra Ranch, LLC in 2016 for aesthetics and is managed by Tierra Piedra Ranch, LLC personnel. Consequently, this area was also sprayed by Tierra Piedra Ranch, LLC personnel on 5/14/20 and 5/15/20.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Attached document does not demonstrate that vegetation around the working area is not project-related disturbance. As comments that described weeds were sprayed, review is approved. However, operator is responsible for controlling weeds within the project area, including areas planted for aesthetics.

2 ☒ CA# 139128

Corrective Action: Erosion controls such as seeding and vegetation establishment are needed to provide long term stabilization on northern and western soil berms. Temporary controls are needed until long term stabilization is achieved.

Date: 04/01/2019

Response: CA COMPLETED

Date of Completion: 05/22/2020

Operator Comment: The North and part of the East berm were recontoured and seeded on 5/21/20. Erosion mats were placed on these areas on 5/22/20 to mitigate stormwater erosional effects. The majority of the East berm, the ~65' of Southern berm managed by Petrox was left because natural vegetation is progressing. These bermed areas were spot sprayed on 5/14/20 for intermittent weed. The rest of the Southern berm and Western Berm were paid for, built by, and are managed by Tierra Piedra Ranch, LLC (as built drawing on file with the COGCC and reattached to this FIRR). Also, see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Can all of Catherine Roy's reports please be sent to Ryan Clark: Ryan@petrox-resources.com as well as Dusty Nystrom and Mike Clark. In addition, the email for Mike Clark (mike.petroxcbm@gmail.com) has been disconnected as of 4 years ago so reports from Catherine Roy are not being received by Petrox office staff! Please use mike.petrox@gmail.com as Mike Clark's new email. Thank you!

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Clark

Signed: \_\_\_\_\_

Title: Engineer

Date: 5/26/2020 11:21:10 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402405486	FIR RESOLUTION SUBMITTED
402405553	Correction Photos
402405554	TP #15-1 as Built Pad

Total Attach: 3 Files