

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402416433

Date Received:  
06/09/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>
.		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901783  
Inspection Date: 05/12/2020 FIR Submit Date: 05/14/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306936

Location Name: MERRY FEDERAL G. U.-M34N6W Number: 10NWNE County: LA PLATA  
Qtrqr: NWNE Sec: 10 Twp: 34N Range: 6W Meridian: N  
Latitude: 37.232586 Longitude: -107.511393

FACILITY - API Number: 05-067-00 Facility ID: 280384

Facility Name: MERRY FEDERAL Number: 2  
Qtrqr: NWNE Sec: 10 Twp: 34N Range: 6W Meridian: N  
Latitude: 37.232586 Longitude: -107.511393

CORRECTIVE ACTIIONS:

1  CA# 139032

Corrective Action: Control weeds. Spot seeding will likely be needed in weed treatment areas after infestation is controlled. Date: 06/01/2020

Response: CA COMPLETED Date of Completion: 05/22/2020

Operator Comment: In response to this corrective action herbicide application was performed on location and interim reclamation. Previous treatment dates are as follows:  
7/20/2016  
7/11/2017

6/7/2018  
6/24/2019

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2  CA# 139033

Corrective Action: Stormwater controls need to be installed using good engineering practices. Stormwater controls need to be selected, sized, installed, and maintained accordingly. CDOT manuals on erosion control demonstrate good engineering practices.

Date: 06/15/2020

Response: CA COMPLETED

Date of Completion: 06/05/2020

Operator Comment: Erosion actions completed are installation of rock rundown and creation of a diversion ditch to direct flow of stormwater see attached.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Corrective actions completed and attached are photos of work at completion of execution of work.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Specialist

Date: 6/9/2020 9:57:52 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402416433	FIR RESOLUTION SUBMITTED
402416437	Weed treatment documentation
402416438	Stormwater control documentation

Total Attach: 3 Files