

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402474660

Date Received:
08/25/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Lindsey Rider</u>	<u>970-285-2600</u>	<u>cogcc.inspections@caerusoilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696201629

Inspection Date: 08/04/2020

FIR Submit Date: 08/11/2020

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335512

Location Name: Mesa Number: C23-697 County: _____

Qtrqtr: NWNE Sec: 23 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.515044 Longitude: -108.184547

FACILITY - API Number: 05-045-00 Facility ID: 335512

Facility Name: Mesa Number: C23-697

Qtrqtr: NWNE Sec: 23 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.515044 Longitude: -108.184547

CORRECTIVE ACTIONS:

1 CA# 141153

Corrective Action: Implement BMPs to prevent commingling of cuttings and topsoil, such that the sources remain separate.

Date: 08/26/2020

Response: CA COMPLETED

Date of Completion: 08/13/2020

Operator Comment: The cuttings and topsoil stockpiles were segregated by moving the cuttings pile away from the topsoil pile. The cuttings were moved to their placement for interim reclamation. Adequate BMPs will be installed in the future to protect topsoil.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 141154

Corrective Action: See "COGCC Comments" for details regarding Interim Reclamation corrective actions

1) Submit by 8/25/2020, attached to a Form 4 Sundry Notice, a reclamation plan to COGCC Reclamation Staff

2) Conduct Inteirm Reclamation pursuant to 1003 Rules by 10/15/2020

2) Submit "Self Audit" information by 8/25/2020

Date: 08/25/2020

Response: CA COMPLETED

Date of Completion: 08/25/2020

Operator Comment: Form 4 (Document # 402474600) was submitted 8/25/20. The C23-697 Interim Reclamation Plan was included as an attachement along with the Self Audit. The intirim reclamation is in progress and is projected to be complete by the 10/15/20 due date.

COGCC Decision: Approved

COGCC Representative: Documents provided per the corrective action

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lindsey Rider

Signed: _____

Title: EHS Lead

Date: 8/25/2020 1:28:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402474660	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files