

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402475746

Date Received:
08/26/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>BAKER DAVID</u>		<u>dbaker@auroramp.com</u>
<u>Fitzgerald, Edie</u>		<u>ediefitzgerald@tcenergyllc.com</u>
<u>Dylan Thomsen</u>		<u>timothy.thomsen@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690200496
Inspection Date: 08/03/2020 FIR Submit Date: 08/04/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 307884

Location Name: APACHE CANYON-634S68W Number: 24NWNE County: LAS ANIMAS
Qtrqr: NWNE Sec: 24 Twp: 34S Range: 68W Meridian: 6
Latitude: 37.074030 Longitude: -104.943110

FACILITY - API Number: 05-071-00 Facility ID: 259100

Facility Name: APACHE CANYON Number: 24-02V
Qtrqr: NWNE Sec: 24 Twp: 34S Range: 68W Meridian: 6
Latitude: 37.074030 Longitude: -104.943110

CORRECTIVE ACTIIONS:

1 CA# 140987

Corrective Action: Comply with Rule 1003.f.

Date: 08/14/2020

Response: CA COMPLETED

Date of Completion: 08/05/2020

Operator Comment: NOXIOUS WEEDS ALONG THE LEASE ROAD WERE TREATED ON 08/05/20.

COGCC Decision: Approved

COGCC Representative:

2 CA# 140988

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 08/28/2020

Response: CA COMPLETED

Date of Completion: 08/26/2020

Operator Comment: THE MAIN LEASE ROAD WAS SURFACE CROWNED TO ESTABLISH SHEET FLOW AND ELIMINATE THE TIRE RUTS AND SURFACE EROSION. THE BREACH IN THE DIRT BERM AND WATERBAR HAS BEEN REPAIRED. THE CUT SLOPE WAS DISTURBED WHEN THE SOIL STOCKPILE WAS REMOVED DURING RECENT REMEDIATION WORK ON THE FILL SLOPE. THE DISTURBANCE WAS SEEDED WITH AN APPROVED CPW SEED MIX AND EROSION CONTROL BLANKETS WERE INSTALLED OVER DISTURBED AREA FOR TEMPORARY SOIL STABILIZATION AND TO PROMOTE THE ESTABLISHMENT OF VEGETATION

COGCC Decision: Approved

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS ARE COMPLETE

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: EDIE FITZGERALD

Signed: _____

Title: SR. ENVIRONMENTAL TECH.

Date: 8/26/2020 2:48:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402475746	FIR RESOLUTION SUBMITTED
402475755	PHOTO LOG

Total Attach: 2 Files