

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402481896

Date Received:

09/03/2020

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Amanda Blanchard</u>	<u>970-385-0696</u>	<u>ablanchard@sginterests.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696201675

Inspection Date: 08/31/2020

FIR Submit Date: 09/01/2020

FIR Status: _____

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 324491

Location Name: Federal 11-90-15 Number: 1 County: _____

Qtrqr: SESW Sec: 15 Twp: 11s Range: 90w Meridian: 6

Latitude: 39.094250 Longitude: -107.437810

FACILITY - API Number: 05-051-00 Facility ID: 324491

Facility Name: Federal 11-90-15 Number: 1

Qtrqr: SESW Sec: 15 Twp: 11s Range: 90w Meridian: 6

Latitude: 39.094250 Longitude: -107.437810

CORRECTIVE ACTIONS:

1  CA# 141644

Corrective Action: Install BMPs to prevent wildlife access to cellar.

Date: 06/13/2020

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator Comment: As noted in the FIRR (402409652), wildlife BMPs have been added to allow wildlife an escape route. Photos taken by inspector show t-post as the escape route. The cellar is only ~3' deep so mice are the only mammals that would potentially get trapped in the cellar. They are able to escape up the t-post. BMPs over well cellars to prevent mice access is not a rule. In addition, the mice would just crawl through the grate if one was added. Other wells in the State of Colorado are not being held to the standard to prevent wildlife access to cellar.

COGCC Decision: **Not Approved**

COGCC Representative: Wildlife BMPs are inadequate.

COGCC Supervisor: Wildlife BMPs are inadequate. Operator's last sentence is not accurate.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Blanchard

Signed:

Title: Env & Reg Manager

Date: 9/3/2020 1:43:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402481896	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files