

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402477797

Date Received:  
08/28/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 5 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696201631

Inspection Date: 08/10/2020

FIR Submit Date: 08/11/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335667

Location Name: N PARACHUTE Number: WF15A-23 County: \_\_\_\_\_  
F23596

Qtrqtr: SENW Sec: 23 Twp: 5S Range: 96W Meridian: 6

Latitude: 39.601606 Longitude: -108.140351

FACILITY - API Number: 05-045- -00 Facility ID: 335667

Facility Name: N PARACHUTE Number: WF15A-23  
F23596

Qtrqtr: SENW Sec: 23 Twp: 5S Range: 96W Meridian: 6

Latitude: 39.601606 Longitude: -108.140351

CORRECTIVE ACTIONS:

4 ☒ CA# 141158

Corrective Action: Implement BMPs to mitigate transport/discharge of impacted materials pursuant to 1002.f rules.

Date: 07/30/2020

Response: CA COMPLETED

Date of Completion: 08/15/2020

Operator Comment: BMPs were added.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

5 ☒ CA# 141159

Corrective Action: Install or repair required BMPs per Rule 1002.f. Continue stormwater managment and implement BMPs as needed to adapt to the site conditions.

Date: 07/14/2020

Response: CA COMPLETED

Date of Completion: 08/15/2020

Operator Comment: BMPs were added.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 8/28/2020 2:53:44 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402477797	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files