

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2020

Submitted Date:

09/10/2020

Document Number:

700300080**FIELD INSPECTION FORM**Loc ID 313550 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8725Name of Operator: BLACK RESOURCES, INCAddress: 320 MUSTANG TRAILCity: GRANBURY State: TX Zip: 76049**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Black, Bill		blackmustang.biz@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224454	WELL	TA	06/14/1990	GW	083-06519	STATE 36-11	TA

General Comment:

Follow up inspection to FIR doc# 700300015 corrective actions. Operator submitted gas analysis with 250 ppm H2S on 5/20/20 to COGCC and Montezuma County LGD.

H2S sign installed at entrance to loc, wind indicator at wellhead, debris removed from around wellhead, dead weed debris removed from pad, new thistle growth noted.

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	H2S wind indicator		
Corrective Action:		Date:	
Type	OTHER		
Comment:	H2S sign on fence post of fence that delineates location. Sign placement distance should be measured from entrance to location.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	new weed growth note (see photo doc)		
Corrective Action:	monitor and control weeds	Date:	
Type	OTHER		
Comment:	Well sign with different 24 hour operator contact information on ground, there should only be one 24 hour operator contact number		
Corrective Action:	remove sign on ground (see photo doc) or use sign and correct operator contact number so it matches the best number to contact operator at any time.	Date:	10/10/2020
Type	TRASH		
Comment:	trash on side of lease road (see photo)		
Corrective Action:	ensure location and access road are kept free of trash and debris	Date:	10/10/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	see phot of sagging and down fencing on south and east sides of location		
Corrective Action:	Repair down and loose sagging fencing	Date:	10/10/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:	adequately mark deadman per rule 1002.a		Date: 10/10/2020
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 224454 Type: WELL API Number: 083-06519 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Corrective Action:

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402485862	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5243821
700300088	PHOTOS 20200826	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5243819