

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2020

Submitted Date:

09/15/2020

Document Number:

700600149

FIELD INSPECTION FORM

Loc ID 309175 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fitzgerald, Edie	719-859-1394	ediefitzgerald@tcenergyllc.com	
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergyllc.com	All Inspections
Mack, Ronald		ronaldmack@tcenergyllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289504	WELL	PR	10/26/2009	GW	071-09205	GOLDEN EAGLE 30-05	EI

General Comment:

This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.

This is an environmental inspection only. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site condition at the time of inspection.

Operator is prohibited from placing non Exploration and Production Waste in produced water tanks.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
Lube Oil	Separator	<= 1 bbl		
Comment: Lube oil spill from liquid ring containment (see attached photos).				
Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 09/30/2020

In Containment: No

Comment:

Pursuant to Rule 907A. Operator shall properly identify and dispose of non-E&P wastes in accordance with state and federal regulations, including storing, treating, and disposing of hazardous waste in accordance with 6 C.C.R. 1007-3. All non-hazardous/non-E&P wastes are considered solid waste which require storage, treatment, and disposal in accordance with 6 C.C.R. 1007-2.

For all waste transported off site for disposal, provide all documentation required by Rule 907.b.(2) A-F. Provide by pdf all invoices, haul tickets, manifests or other records to document the requirements A - F.

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 289504 Type: WELL API Number: 071-09205 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	293755	2059556	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700600151	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5249903