

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2020

Submitted Date:

09/15/2020

Document Number:

696201765

FIELD INSPECTION FORM

Loc ID: 335981 Inspector Name: Trujillo, Aaron On-Site Inspection: 2A Doc Num: _____

Operator Information:
 OGCC Operator Number: 10091
 Name of Operator: BERRY PETROLEUM COMPANY LLC
 Address: 5201 TRUXTUN AVENUE #100
 City: BAKERSFIELD State: CA Zip: 90339

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 2 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		jcobb@bry.com	
		jarmstrong@bry.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296741	WELL	AL	01/11/2018	LO	045-16112	CHEVRON 5-27D	RI
296742	WELL	AL	01/11/2018	LO	045-16113	CHEVRON 5-28D	RI
296743	WELL	AL	10/24/2017	LO	045-16114	CHEVRON 5-16D	RI
296744	WELL	AL	10/24/2017	LO	045-16115	CHEVRON 5-24D	RI
296745	WELL	AL	10/24/2017	LO	045-16116	CHEVRON 5-26D	RI
296746	WELL	AL	10/24/2017	LO	045-16117	CHEVRON 35-1D	RI
335981	LOCATION	AL			-	Chevron D05 696	RI

General Comment:

On 9/14/2020, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at Berry Petroleum's Chevron D05 696 location in Garfield County, Colorado.

This inspection is to document compliance for the following corrective actions from Inspection #696201150, and #69240231: 1004.e: Weed Management

The following compliance issues were observed during this inspection: 1004.e: Noxious weeds remain evident on Location.

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected FacilitiesFacility ID: 296741 Type: WELL API Number: 045-16112 Status: AL Insp. Status: RIFacility ID: 296742 Type: WELL API Number: 045-16113 Status: AL Insp. Status: RIFacility ID: 296743 Type: WELL API Number: 045-16114 Status: AL Insp. Status: RIFacility ID: 296744 Type: WELL API Number: 045-16115 Status: AL Insp. Status: RIFacility ID: 296745 Type: WELL API Number: 045-16116 Status: AL Insp. Status: RIFacility ID: 296746 Type: WELL API Number: 045-16117 Status: AL Insp. Status: RIFacility ID: 335981 Type: LOCATION API Number: - Status: AL Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ In _____ Cropland: perennial forage _____

Weeds present **Fail** _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Previous inspections observed Noxious weeds (Musk thistle, Houndstongue, Mullein) have established on the Location. Inspections required Operator to comply with Rule 1004.e, and to conduct ongoing weed monitoring/management efforts.

It was observed in this inspection that initial weed management efforts appear to have been conducted. However, additional thistle and houndstongue rosettes were observed on the Location and access road; plants likely germinated after initial weed management efforts.

Inspection #692402317 required that if further weed treatment or activities are indicated by monitoring review, complete such activities by 11/15/20; This corrective action remains applicable.

Corrective Action: **Comply with Rule 1004.e and conduct noxious weed management and monitoring to prevent further noxious weed establishment. Management efforts will need to be ongoing until final reclamation has passed.**

Date **11/15/2020**

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402489450	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5247454
696201766	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5247443