

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402499119

Date Received:

09/29/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Madison, Randy</u>	<u>575-445-6706/575-420-1120</u>	<u>rmadison@wapitienergy.com</u>
<u>Middlebrook, Sonny</u>	<u>575-445-6724/575-445-8610</u>	<u>smiddlebrook@wapitienergy.com</u>
<u>Berry, Matthew</u>	<u>575-445-6785/505-652-8275</u>	<u>mberry@wapitienergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695103311

Inspection Date: 09/23/2020

FIR Submit Date: 09/23/2020

FIR Status: _____

Inspected Operator Information:

Company Name: WAPITI OPERATING LLC

Company Number: 10351

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

LOCATION - Location ID: 308210

Location Name: VPR C-635S66W Number: 15SENW County: LAS ANIMAS

Qtrqr: SENW Sec: 15 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.000860 Longitude: -104.770180

FACILITY - API Number: 05-071-00 Facility ID: 264073

Facility Name: VPR C Number: 45

Qtrqr: SENW Sec: 15 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.000860 Longitude: -104.770180

CORRECTIVE ACTIONS:

1 CA# 142278

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Date: 10/23/2020

Response: CA COMPLETED

Date of Completion: 09/24/2020

The stain around the well head has been removed and cleaned-up. The soil was properly disposed of per rule.

Operator Comment: _____

COGCC Decision: _____

COGCC Representative: _____

2 CA# 142279

Corrective Action: PLUMB BRADENHEAD TO USRFACE, COMPLY WITH RULE 608.e.

Date: 10/23/2020

Response: CA COMPLETED

Date of Completion: 09/24/2020

Operator Comment: Braden head has been plumbed to the surface.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 142280

Corrective Action: REMOVE UNUSED EQUIPMENT, COMPLY WITH RULE 603.f.

Date: 10/23/2020

Response: CA COMPLETED

Date of Completion: 09/24/2020

Operator Comment: The wood that was on location has been removed .

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All of the corrective actions have been addressed and taken care of.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy Madison Signed: _____

Title: HSE Specialist Date: 9/29/2020 8:35:14 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402499122	Bradenhead and Stain Cleaned-up
402499124	Area cleaned up
402499125	Trash removed

Total Attach: 3 Files