

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/29/2020

Submitted Date:

09/29/2020

Document Number:

699302648

FIELD INSPECTION FORM

Loc ID 448913 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10503
Name of Operator: RED HAWK PETROLEUM LLC
Address: 575 N DAIRY ASHFORD STE 201
City: HOUSTON State: TX Zip: 77079

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dshepard@pacificenergydevelopment.com	All Inspections - formerly CONDOR

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448912	WELL	XX	04/16/2019		123-44068	L.E. Gerkin 14H	ND

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 448912 Type: WELL API Number: 123-44068 Status: XX Insp. Status: ND

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 9/29/2020 at approximately 1000 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Red Hawk Petroleum LLC location: L.E. Gerkin at Location #448913 in Weld County Colorado. While there, I observed Multi-Well pad. I didn't check this well on previous inspection. At the time of Inspection location construction has been paused and no drilling has tanken place on location. Form 42(CN) Doc # 402277153 was submitted on 1-3-2020 and is approved. During this inspection no compliance issues were observed: See attached photos. Location is dry, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	09/29/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302649	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5259048