

HILL RANCH 36-10 API# 05-071-08254 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 22, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103246



PHOTO 1: THE SOUND WALL PANEL THAT WAS ON THE GROUND TO ACCESS THE ENGINE SKID WAS REINSTALLED SURROUNDING THE ENGINE SKID.

HILL RANCH 36-10 API# 05-071-08254 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 22, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103246



PHOTO 2: THE SOUND WALL PANEL THAT WAS ON THE GROUND WAS REINSTALLED SURROUNDING THE ENGINE SKID.