

APACHE CANYON 10-01 API# 05-071-08277 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 03, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103256



PHOTO 1: THE (2) RISERS ARE IN USE AND EACH ONE HAS BRASS TAG WHICH ARE VISABLE IN THE FIELD INSPECTION REPORT DOC # 695103256 PHOTO # 3 DOC # 695103260. THE NUMBERING SYSTEM IS STAMPED ON IT TO IDENTIFY THE DRIP RISERS. AC-58 AND AC-59 ARE ABBREVIATED FOR APACHE CANYON DRIP # 58 AND APACHE CANYON DRIP # 59.

APACHE CANYON 10-01 API# 05-071-08277 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 03, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103256



PHOTO 2: THERE IS A HIGH PRESSURE DRIP RISER AND A LOW PRESSURE DRIP RISER THAT ARE IN USE AND WERE MARKED WITH AN ORANGE MARKING PIN FOR ADDITIONAL IDENTIFICATION.

APACHE CANYON 10-01 API# 05-071-08277 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 03, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103256



PHOTO 3: THIS IS AN ELECTRICAL CONDUIT PULL POINT AND NOT A " RISER". THE END CAP WAS IMPROVED.

APACHE CANYON 10-01 API# 05-071-08277 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 15, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103256



PHOTO 4 : THE COLORADO PARKS AND WILD LIFE (CPW) HAVE ON GOING TREE CLEARING OPERATIONS IN THE BOSQUE DEL OSO STATE WILDLIFE AREA. THESE TREE DEBRIS WERE DROPPED OFF ON LOCATION BY THE LOGGING COMPANY. TIMBER CREEK RELOCATED DISCARDED TREE CUTTINGS FROM WELL PAD TO THE NEAR BY SLASH PILES.

APACHE CANYON 10-01 API# 05-071-08277 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 03, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103256



PHOTO 5 : THE IMPACTED SOIL NEAR THE COMPRESSOR INSIDE THE SOUND WALLS HAS BEEN CLEANED UP.

APACHE CANYON 10-01 API# 05-071-08277 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 05, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103256



PHOTO 6 : THE NOXIOUS WEEDS ON THE WELL PAD AND ADJACENT TO THE LEASE ROAD WEST OF LOCATION WERE TREATED ON 09/05/20.

APACHE CANYON 10-01 API# 05-071-08277 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 05, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103256




PHOTO 7 : THE COLORADO PARKS AND WILD LIFE (CPW) HAVE ON GOING TREE CLEARING OPERATIONS IN THE BOSQUE DEL OSO STATE WILDLIFE AREA. THE NOXIOUS WEEDS IN THE FOREST (UNDISTURBED NATURAL VEGETATION) IS THE RESPONSIBILITY OF THE CPW TO MANAGE.

APACHE CANYON 10-01 API# 05-071-08277 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 05, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103256



PHOTO 8 : THE COLORADO PARKS AND WILD LIFE (CPW) HAVE ON GOING TREE CLEARING OPERATIONS IN THE BOSQUE DEL OSO STATE WILDLIFE AREA. THE NOXIOUS WEEDS IN THE FOREST (UNDISTURBED NATURAL VEGETATION) IS THE RESPONSIBILITY OF THE CPW TO MANAGE.

APACHE CANYON 10-01 API# 05-071-08277 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 05, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103256




PHOTO 9 : THE COLORADO PARKS AND WILD LIFE (CPW) HAVE ON GOING TREE CLEARING OPERATIONS IN THE BOSQUE DEL OSO STATE WILDLIFE AREA. THE NOXIOUS WEEDS IN THE FOREST (UNDISTURBED NATURAL VEGETATION) IS THE RESPONSIBILITY OF THE CPW TO MANAGE.