

Inspection Photos
Location Name: Stroh #2
Location ID: 323006



Production facility




Wellhead

Inspection Photos

Location Name: Stroh #2
Location ID: 323006



Battery sign emergency contact number



Calibration card