

TEP ROCKY MOUNTAIN LLC
PA-66S95W 33NESE
Location ID: 335303



TEP ROCKY MOUNTAIN LLC
PA-66S95W 33NESE
Location ID: 335303



2- 2" hard line piping off of the north west edge across from the separators.



2- 2" hard line piping off of the north west edge across from the separators.

TEP ROCKY MOUNTAIN LLC
PA-66S95W 33NESE
Location ID: 335303



Weeds in middle of roadway cleared.