

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402534565

Date Received:

11/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

.Grizzly

sghan@grizzlyenergyllc.com

.Grizzly

aaxelson@grizzlyenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700701756

Inspection Date: 10/23/2020

FIR Submit Date: 10/23/2020

FIR Status: _____

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 418772

Location Name: Kaufman pad 6 Number: 21A-24-692 County: _____

Qtrqtr: SWNE Sec: 24 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.516058 Longitude: -107.614354

FACILITY - API Number: 05-045-00 Facility ID: 418772

Facility Name: Kaufman pad 6 Number: 21A-24-692

Qtrqtr: SWNE Sec: 24 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.516058 Longitude: -107.614354

CORRECTIVE ACTIONS:

1 CA# 143930

Corrective Action: repair hole in containment

Date: 11/13/2020

Response: CA COMPLETED

Date of Completion: 10/30/2020

Operator Comment: containment repair completed

COGCC Decision: _____

CA completed

<p>Repaired berm, removed wattles, replaced check dams, raked and seeded perceived runoff area, and rerouted discharge point.</p>

--

Date: 11/17/2020 1:52:56 PM

Page 2 of 2