

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2020

Submitted Date:

11/19/2020

Document Number:

700900348**FIELD INSPECTION FORM**Loc ID 320451 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|----------------|----------------------------|---------------------------------|
| James, Steven | (303) 893-2438 | steve@westernoperating.com | All Inspections |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____ Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | pipe | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|---|-------|------------------|
| Equipment: | | | corrective date |
| Type: Pump Jack | # 1 | | |
| Comment: | Spills/Releases/stained soil. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. Corrective Action Date 12/18/2020 to remove stained soil See attached photo #2 | | Date: 12/18/2020 |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Friday November 4, 2020 at approximately 9:30am, I, Inspector Chane Finkenbinder, conducted an on-site inspection at Linnbur 6-43, Western Operating Company), at API #001-09167 in Adams County Colorado.</p> <p>While there, I observed in Production,</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Spills/Releases/stained soil. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. Corrective Action Date 12/18/2020 to remove stained soil See attached photo #2</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | finkenbc | 11/19/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 700900349 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294660 |