

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2020

Submitted Date:

11/23/2020

Document Number:

700900350**FIELD INSPECTION FORM**Loc ID 320456 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203813	WELL	PR	03/13/1998	OW	001-09373	LINNEBUR 6-23	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Adequate
Corrective Action:	Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Spills/Releases/stained soil.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. Corrective Action Date 12/18/2020 to remove stained soil See attached photo #2		Date: 12/18/2020

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 203813 Type: WELL API Number: 001-09373 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Friday November 4, 2020 at approximately 9:40am, I, Inspector Chane Finkenbinder, conducted an on-site inspection at Linnbur 6-23, Western Operating Company), at API #001-09373 in Adams County Colorado.
 While there, I observed in Production,
 During this inspection the following possible compliance issues were observed:
 Spills/Releases/stained soil. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. Corrective Action Date 12/18/2020 to remove stained soil See attached photo #2

finkenbc

11/23/2020

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900351	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5296080