

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2020

Submitted Date:

11/24/2020

Document Number:

693802538

**FIELD INSPECTION FORM**

Loc ID 322095 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10754  
Name of Operator: FOUR CORNERS ENERGY LLC  
Address: 531 E 770 N  
City: OREM State: UT Zip: 84097

**Findings:**

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Telecky, Barbara		btelecky@blm.gov	Durango
Pesicka, Conor		conor.pesicka@state.co.us	
Williams, Larry	(801) 657-5780	larry@thesummitcompanies.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208955	WELL	SI	01/01/2016	GW	033-06060	FEDERAL 1-19	SI

**General Comment:**

COGCC staff performed a field inspection on 11/19/2020.  
Issues were found requiring corrective action. See inspection text and photos for details.  
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective ActionL			Date:
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 12/31/2020
Type	BATTERY		
Comment:			
Corrective Action:			
Emergency Contact Number:			
Comment:	801-657-5780 or 435-279-7144		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds		
Corrective Action:	Comply with Rule 603.f .		Date: 12/05/2020
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	STEEL AST		37.619257,-108.992058
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 208955 Type: WELL API Number: 033-06060 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well shut in 1/2016. No MIT on record.  
Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 12/31/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402540009	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5297943">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5297943</a>
693802552	Inspewction photos 11/19/2020	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5297936">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5297936</a>