

Location			
Lease Road:			
Type	Access		
comment:	in crop		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	No sign displayed at well. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 02/28/2021
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Weeds/debris inside wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 603.f.		Date: 02/28/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 1	corrective date	
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 294845 Type: WELL API Number: 123-25562 Status: SI Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: SICorrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Monday, November 30, 2020 at approximately 10:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at SCHMUNK 31-41 (Great Western Oil & Gas), at location #: 309902 in WELD COUNTY Colorado. While there, I observed a shut in wellhead. During this inspection the following possible compliance issues were observed: 1. No sign is displayed at wellhead to indicate wellhead name/operator/emergency contact #, etc. Install sign to comply with Rule 210.b. (Corrective Action Date: February 28, 2021) See attached photo #1. 2. Weeds/debris inside wellhead fencing. Remove and comply with Rule 603.f. (Corrective Action Date: February 28, 2021) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	11/30/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402543087	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5300496
679603488	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5300487