

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/28/2020

Submitted Date:

12/29/2020

Document Number:

700702061

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
316158 _____ Ramsey, Scott _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
operating, 31		kfreeman@31operating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232254	WELL	PR	05/31/2000	GW	103-09925	WRD UNIT 20-33	SI

General Comment:COGCC Inspection Report Summary

On 12/22/20, I, Inspector Scott Ramsey, conducted a Safety and compliance inspection at 31 Operating 20-33 at Location # 316158 in Rio Blanco county Colorado.

This is a limited inspection for Safety and Compliance.

While there, I observed that location has not been visited in quite some time, nor had the access roads been plowed.

I spoke with Leven who has worked for 31 operations at the lay down yard. He stated that the compressors were pulled out of his field back in October and that he and other pumpers on his side of the field went through and shut all of the wells in November. He had also given me a map of the field and pointed out that he was not sure of some locations that had supply gas running to the burners had been shut off. He also stated that they did NOT evacuate any of the flow lines of fluid. He did not go out to the field with me, he suggested that I could shut the supply gas off if I came across any that needed it. He also stated that all of their phone numbers had been disconnected. This is a summary of inspection report.

Location

Lease Road:

	Type Access		
comment:	Snow covered/not plowed		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#			corrective date
Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date: _____
Bird Protectors	# 2			
Comment:				
Corrective Action:				Date: _____
Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date: _____
Pump Jack	# 1			
Comment:				
Corrective Action:				Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date: _____

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 232254 Type: WELL API Number: 103-09925 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702096	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317857