

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Electric

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: Electric motor

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 240980 Type: WELL API Number: 123-08768 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Annual Bradenhead test is not current. Contact COGCC engineering.

01/09/2021

Corrective Action: Comply with 341 c.

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 12/30/20 at approximately 1115 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- B C Hopkins 31-19 (1-67) 3 Company Name- Fritzler Resources INC API- 05-123-08768 In Weld County Colorado. While there, I observed producing well. During this inspection the following possible compliance issues were observed: Annual Bradenhead test is not current. Contact COGCC engineering. Comply with 341 c. 1/9/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	12/30/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502092	Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318982