

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2020

Submitted Date:

12/24/2020

Document Number:

700404676**FIELD INSPECTION FORM**Loc ID 311791 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Heil, John		john.heil@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228594	WELL	SI	12/01/2019	OW	103-05500	MCLAUGHLIN SR 6	PR

**General Comment:**

A follow up inspection of FIR document 7004004645 dated 12-18-2020.

- 1) Report past due monthly operations on Form 7. Complete by 7-15-2020.
- 2) Provide an emergency phone number that is answered. Photo 5. Complete by 12-19-2020.
- 3) Contact the COGCC EPS staff in reference to the oil spill. Photos 1 to 4.
- 4) Venting of gas from the open casing.

On arrival the inspector observed the pump jack was actively pumping and the oil spill had extended an additional ~3 feet since the prior inspection. The emergency phone numbers posted on the sign, 800-209-9762, was called at 11:12. No one answered and the call disconnected after 10 rings. In addition the following Lasso numbers were called: 254-727-0435, 970-210-9509, 970-457-0006, 469-585-6359, and 972-810-1031. None were answered. One number, 469-585-6359, allowed a voice message for which a message was left.

Next the inspector received authorization from COGCC managment to shutoff the power to the pump jack and contain the spill. When the berm was almost completed a current or former employee of 31 Operating came to the location.

This is a summary of inspection report 700404676.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Corrective Action: 

Date: 12/19/2020

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Crude Oil	WELLHEAD			
Comment:	Oil spill from over flowed cellar. See photos.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date:

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	Gas venting out open casing.		
Corrective Action:	Gas being vented or flared during non-upset condition without prior approval from COGCC.	Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 228594 Type: WELL API Number: 103-05500 Status: SI Insp. Status: PR**Producing Well**Comment: Last reported monthly operations were for May 2020. Report past due monthly operations.Well was producing until the inspector shut off the power to the pump jack.Corrective Action: Submit required Form 7(s) to COGCC per rule 309.Date: 07/15/2020

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402560509	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5316228">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5316228</a>
700404677	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5316227">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5316227</a>