

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/11/2021

Submitted Date:

01/12/2021

Document Number:

700404936

FIELD INSPECTION FORMLoc ID 465575 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465574	WELL	DG	08/09/2019		103-12363	Weaver Ridge 14-11H	DG
465576	WELL	XX	06/21/2019		103-12364	Weaver Ridge 14-14H1	ND
465577	WELL	DG	08/09/2019		103-12365	WEAVER RIDGE 14-14H2	DG

General Comment:

A follow up inspection of documents

1) 700403665 dated 9-29-2020.

2) 700404575 dated 12-14-2020.

The following compliance issues are uncompleted:

1) Well head signs were added at the location entrance before 12-14-202. The signs need moved to their individual well. A sign for Weaver Ridge 14-14H1 (05-103-12364) was added, but the well hasn't been drilled. A sign for Weaver Ridge 14-14H2 (05-103-12365) is missing. Photo 2 & 3. Complete by 12-1-2020.

This is a summary of inspection report 700404936.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well head signs were added at the location entrance. The signs need moved to their individual well. A sign for Weaver Ridge 14-14H1 (05-103-12364) was added, but the well hasn't been drilled. A sign for Weaver Ridge 14-14H2 (05-103-12365) is missing.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/01/2020

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 465574 Type: WELL API Number: 103-12363 Status: DG Insp. Status: DG**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: DG in August 2019.

Corrective Action: _____ Date: _____

Facility ID: 465576 Type: WELL API Number: 103-12364 Status: XX Insp. Status: ND**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Permit expires 6-20-2021.

Corrective Action: _____ Date: _____

Facility ID: 465577 Type: WELL API Number: 103-12365 Status: DG Insp. Status: DG**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: DG in August 2019.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: 7" of snow on location.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Drilling PitLined: YES

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:Liner Type: PlasticLiner Condition: Adequate

Comment: Covered in snow.

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700404937	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327807