

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402571557

Date Received:
01/11/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mack, Ronald</u>	<u>719-859-4896</u>	<u>rmack@ogrisop.com</u>
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>efitzgerald@ogrisop.com</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695103273
Inspection Date: 09/11/2020 FIR Submit Date: 09/12/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309175

Location Name: GOLDEN EAGLE-633S67W Number: 30SWNW County: LAS ANIMAS
Qtrqtr: SWN Sec: 30 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.145232 Longitude: -104.934732

FACILITY - API Number: 05-071-00 Facility ID: 289504

Facility Name: GOLDEN EAGLE Number: 30-05
Qtrqtr: SWN Sec: 30 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.145232 Longitude: -104.934732

CORRECTIVE ACTIONS:

1 CA# 141978
Corrective Action: COMPLY WITH RULE 603.f. Date: _____

Response: CA COMPLETED

Date of Completion: 01/06/2021

Operator Comment: THE UNUSED EQUIPMENT WAS REMOVED FROM THE LOCATION. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 CA# 141979

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A., Properly dispose of oily waste in accordance with Rule 907.e, Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. CA DATE 9/13/20.

Date: _____

Response: CA COMPLETED

Date of Completion: 01/06/2021

Operator Comment: THE IMPACTED SOIL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED AND PROPERLY DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 CA# 141980

Corrective Action: COMPLY WITH RULE 603.f.

Date: _____

Response: CA COMPLETED

Date of Completion: 01/06/2021

Operator Comment: THE PIECES OF WOOD THAT WERE DISCARDED ON SITE WERE RETRIEVED AND PROPERLY DISPOSED OF. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald Signed: _____

Title: Sr. Environmental Tech. Date: 1/11/2021 11:54:09 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402571557	FIR RESOLUTION SUBMITTED

Total Attach: 2 Files