

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402576516

Date Received:  
01/15/2021

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mack, Ronald</u>	<u>719-859-4896</u>	<u>rmack@ogrisop.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>efitzgerald@ogrisop.com</u>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 690200650  
Inspection Date: 09/11/2020 FIR Submit Date: 09/14/2020 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

**LOCATION** - Location ID: 308221

Location Name: GOLDEN EAGLE-633S67W Number: 21SWNE County: LAS ANIMAS  
Qtrqr: SWNE Sec: 21 Twp: 33S Range: 67W Meridian: 6  
Latitude: 37.160140 Longitude: -104.889480

**FACILITY** - API Number: 05-071-00 Facility ID: 264236

Facility Name: GOLDEN EAGLE Number: 21-07  
Qtrqr: SWNE Sec: 21 Twp: 33S Range: 67W Meridian: 6  
Latitude: 37.160140 Longitude: -104.889480

**CORRECTIVE ACTIONS:**

1  CA# 142076

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 01/08/2021

Operator Comment: THE BAR DITCH WAS RECONFIGURED TO ELIMINATE THE EROSION AND THE SOIL WAS COMPACTED WITH THE TIRE OF THE BACKHOE FOR STABILIZATION. THE SEDIMENT ACCUMULATION IN THE CULVERT INLET WAS REMOVED. THE BAR DITCH WAS DOMINATED TO RECEIVE STORMWATER RUN OFF FROM THE UPLAND WATERSHED. THE EROSION ON THE FILL SLOPE WAS BACK FILLED AND THE SOIL WAS COMPACTED.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: Sr. Environmental Tech.

Date: 1/15/2021 1:30:31 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402576516	FIR RESOLUTION SUBMITTED
402576527	PHOTO LOG

Total Attach: 2 Files