



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign is not posted at well.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/23/2021

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: Panel

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Flow Line	# 1				
Plunger Lift	# 1				
Bradenhead	# 1	Bradenhead valve is exposed at surface.			

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Tank battery #443959				
Corrective Action:					Date:

**Paint**

Condition

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: _____

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date: _____

**Flaring:**

Type		
Comment:		
Corrective Action:		Date: _____

**Inspected Facilities**

Facility ID: 287126 Type: WELL API Number: 123-27386 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Thursday 1/21/2021 at approximately 13:15 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Anadarko Frank 9-31 location #302228 in Weld County, Colorado.                      While there, I observed that there was no sign posted at the wellhead. During this inspection the following possible compliance issues were observed: Rule 605.d. with a corrective action date of 4/23/2021.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of the inspection report.</p>	petersont	01/21/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697002885	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334839">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334839</a>